### MC22 - Main Powered



## INSTALLATION INSTRUCTIONS

#### Step 1

Remove the 4x socket head screws to separate the base and the main assembly.

### Step 2

Secure base to the mounting surface.



# Step 3

Place main assembly onto the base and secure using 4x socket head screws from Step 1.

#### Step 4

Your MC22 is now ready to be connected!



