





**MC22**



White (Positive)  
Black (Negative)

**Electrical Characteristics**

**Voltage In**  
12 - 16 VDC

**Power**  
19.5W @ 12VDC


**INSTALLATION INSTRUCTIONS**

**Step 1**

Remove the 4x socket head screws to separate the base and the main assembly.

**Step 2**

Secure base to the mounting surface.



**Step 3**

Place main assembly onto the base and secure using 4x socket head screws from Step 1.

**Step 4**

Your Machine Light is now ready to be connected!

